



# CODE ENFORCEMENT BOARD HEARING AGENDA

APRIL 25, 2017 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

### CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

**Note:** If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

**Board Members:** Patrick McGee, **Chair •** Mark Booth, **Vice Chair •** Joan Hinton

- Lakhi Mohnani Peter Cooper Chris Evert Jonathan Keith William Marx Robert Smith (alternate) Michael Madfis (alternate) Jonathan Keith (alternate)
- Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

------

### HEARING SCHEDULED

-----

CASE NO: CE15092003 CASE ADDR: 1824 SE 1 AV

OWNER: KIENZLE, ROBERT F &

KIENZLE, LYBBI

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. AN INTERIOR ALTERATION WHICH HAS SUB DIVIDED THIS SINGLE FAMILY RESIDENCE INTO AN ILLEGAL DUPLEX WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. WINDOWS WERE ALSO REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15100621

CASE ADDR: 2424 SE 17 ST # 309-B OWNER: APELQUIST, JARRETT P

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERATIONS MADE SUCH AS A KITCHEN REMODEL.
- 2. BATHROOM REMODEL.
- 3. WINDOWS REPLACED.
- 4. WASHER AND DRYER.

INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16051743

CASE ADDR: 1905 N OCEAN BLVD E6B

OWNER: VIVANCO ESCAFFI HOLDING GROUP

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

# FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

# FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16061361

CASE ADDR: 3051 NE 48 ST # 107

OWNER: MACRI, MELISSA

MEYER, NANCY

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

# FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16081198

CASE ADDR: 2404 NE 33 AV # 10 OWNER: 2404 NE 33 AVE #10 LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERATIONS MADE TO THE KITCHEN, BATHROOM, ELECTRICAL HI-HAT LIGHTING.
- 2. TANKLESS WATER HEATER INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16091879

CASE ADDR: 4280 GALT OCEAN DR # 10J

OWNER: PORTER, GEORGE E

RITZ, MELINDA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. THE INTERIOR DEMOLITION OF WALLS, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111239
CASE ADDR: 2455 NE 51 ST

OWNER: MAYBURY MANSIONS ASSN INC

% KOPKIN, MITCHELL W & MARILYN S

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED

PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17030704

CASE ADDR: 4143 N OCEAN BLVD # 202

OWNER: MANOLE, GHEORGHE INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS OF THE BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16090053 CASE ADDR: 3206 NE 19 ST

OWNER: ZEMAN, ALLEN R & ANDREA H

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INSTALLED ACCORDION STORM SHUTTERS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. PLUMBING FIXTURE FOR INTERIOR KITCHEN.
- 2. WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. ELECTRICAL RECEPTACLE IN LAUNDRY AREA.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6)

GFI'S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS

\_\_\_\_\_\_

CASE NO: CE15100741
CASE ADDR: 964 NW 24 AVE

OWNER: NFU PROPERTIES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ONGOING INTERIOR REMODELING INCLUDING THE REMOVAL AND REINSTALLATION OF ELECTRICAL, PLUMBING AND MECHANICAL FIXTURES AND SYSTEMS.

### FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN
ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN
THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:
1. THE CONDENSOR UNIT HAS BEEN REMOVED AND PENDING
INSTALLATION. (COMPLIED)

### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED 2 EXTERIOR DOORS WITHOUT A PERMIT.

### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. PLUMBING FIXTURES HAVE BEEN REMOVED AND REPLACED.

#### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. ELECTRICAL FIXTURES, SWITCHES AND OUTLETS HAVE BEEN REMOVED AND REPLACED.

### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

# FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

------

CASE NO: CE16111512 CASE ADDR: 835 SW 18 ST

OWNER: WASHINGTON, BRANDON H

INSPECTOR: JOSE ABIN

### VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. COMMENCEMENT OF REMODELING ON APPLIED ONLY

PERMITS.

2. CMU OVER WALL A/C OPENING.

### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. WINDOWS REPLACED.
- 2. DOOR REPLACED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16120522 CASE ADDR: 1320 SW 23 AV OWNER: BRANDON, MARY L &

BRANDON, RUSSELL L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED ACCORDION HURRICANE SHUTTER SYSTEM.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. FENCES AT PERIMETER AND BACK OF PARCEL.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE16122275

CASE ADDR: 2649 GULFSTREAM LN

OWNER . GLIDDEN, TIMOTHY J & LISA C

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR RENOVATIONS.
- 2. INSTALLED TILE BACKER IN KITCHEN FOR BACKSPLASH.
- 3. INSTALLED TILE BACKER IN BATHROOM WET AREAS.
- 4. ENCLOSED CARPORT.
- 5. REAR PORCH ROOF HAS NOT BEEN INSTALLED TO CODE AND REQUIRES ENGINEERING.
- 6. INSTALLED PAVERS AT REAR PORCH IN EXCESS OF 200 SOUARE FEET.

- 7. REBUILT DOCK.
- 8. INSTALLED NEW EXTERIOR DOORS.
- 9. CLOSED WINDOWS ON EXTERIOR WALL ENVELOPE.

#### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED SPLIT CENTRAL A/C SYSTEM.
- 2. INSTALLED NEW KITCHEN EXHAUST HOOD.
- 3. INSTALLED MECHANICAL VENTILATION IN BATHROOMS.
- 4. INSTALLED DUCT WORK FOR CENTRAL A/C SYSTEM.

#### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS FOR GLAZED OPENINGS:

- 1. INSTALLED NEW WINDOWS.
- 2. INSTALLED NEW GLAZED DOORS.
- 3. INSTALLED NEW SLIDING GLASS DOORS.

### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED NEW KITCHEN FIXTURES.
- 2. INSTALLED NEW BATHROOM FIXTURES.
- 3. INSTALLED NEW WATER HEATER.

# FBC(2014) 105.3.1.4.5

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. WIRED NEW CIRCUITS FOR LIGHTING.
- 2. NEW CIRCUITS TO SERVICE CENTRAL A/C.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE16121267
CASE ADDR: 627 NE 17 WY
OWNER: ENRIGHT, KEVIN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF SECURITY BARS AT LEFT ELEVATION SLIDING GLASS DOOR. NO PERMIT IN PERMIT HISTORY.

# FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS FOR GLAZED OPENINGS:

1. INSTALLATION OF WINDOWS. NO PERMIT FOR NEW INSTALLATION OF WINDOWS.

### FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF DISCONNECT IN ELECTRICAL ROOM.
  NO PERMIT IN HISTORY FOR SAID INSTALLATION.
- 2. INSTALLATION OF CCTV. NO PERMIT IN HISTORY OF INSTALLATION.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:
WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A
PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL
BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED
FOR NEW DWELLINGS.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

#### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF 4 UNIT APARTMENTS TO 5 UNIT APARTMENTS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

------

CASE NO: CE16070231

CASE ADDR: 500 E DAYTON CIR OWNER: MUSGETTILANE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM RENOVATIONS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

------

CASE NO: CE16110369 CASE ADDR: 800 SW 18 ST

OWNER: LITTLE, RICHARD EDGAR

DE SOUSA, MARIZA PEREIRA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

1. THE ROOF ON THIS HOUSE HAS BEEN REPLACED

WITHOUT PERMIT.

\_\_\_\_\_\_

CASE NO: CE17010662
CASE ADDR: 1512 NE 4 AV
OWNER: ALVAREZ, VICTOR
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMOVED EXISITING SODDED AREA

2. PAVED THE WHOLE AREA.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS

CASE NO: CE17011037 CASE ADDR: 2656 NE 34 ST

OWNER: HEMPHILL, VIRGINIA D C

COFFEY, GINGER

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. WOOD FENCE INSTALLED OR ANY PART OR SECTION OF AN EXISTING WOOD FENCE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

-----

RETURN HEARING (OLD BUSINESS)

\_\_\_\_\_\_

CASE NO: CE15061198
CASE ADDR: 1616 SE 2 CT
OWNER: FINN, ZACHARY
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVERS INSTALLED ON DRIVEWAY AND SWALE AREA.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15062080

CASE ADDR: 4881 NW 9 TER

OWNER: CHARLES, ANNEMISE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

WINDOW OPENING WAS ENCLOSED.
 CENTRAL A/C UNIT WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15071410 CASE ADDR: 2427 NE 8 ST

OWNER: JAMES, GORDON D & JUSTINE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CARPORT WAS ENCLOSED AND CONVERTED INTO A

GARAGE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

-----

CASE NO: CE15121013
CASE ADDR: 1633 SW 9 AV
OWNER: BERRY, TIMOTHY
FOSTER, ANDREW L

MADIO CARDACOUEL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. POOL HEATER INSTALLATION.

2. OUTDOOR SECURITY CAMERAS INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15122078
CASE ADDR: 2360 NW 20 ST

OWNER: REYNOLDS, JOENATHAN CINSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. EXTERIOR DOORS REPLACEMENT.

2. KITCHENS AND BATHROOMS REMODELED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15122079
CASE ADDR: 2374 NW 20 ST

OWNER: REYNOLDS, JOENATHAN C

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. EXTERIOR DOORS REPLACEMENT.

2. KITCHEN AND BATHROOMS REMODELED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16051188
CASE ADDR: 1201 NW 16 CT

OWNER: CHEVEULON, NERUBIN H/E

CHEVEULON, LEDILE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

------

CASE NO: CE16080549
CASE ADDR: 5581 NE 28 AVE
OWNER: DESIMONE, MICHAEL
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTION OF WOOD DECK IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16090072 CASE ADDR: 713 NW 4 AVE

OWNER: STS GROUP USA INC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM RENOVATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE16091583 CASE ADDR: 2140 SW 36 AV

OWNER: AGOSTINHO, MONICA

PIRES, MARCOS ANDRE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW DRIVEWAY CONSTRUCTION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

.\_\_\_\_\_

CASE NO: CE16101628
CASE ADDR: 805 SW 16 ST
OWNER: EIGHT O FIVE LLC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BATHROOM RENOVATION.

2. BATHROOM ADDITION.

3. FRONT PORCH AND CARPORT ENCLOSURE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16101750

CASE ADDR: 3310 NE 16 ST

OWNER: LOMWARD GROUP LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. METAL GATE INSTALLED ON THE SIDE OF THE HOUSE.

- 2. ABOVE GROUND POOL INSTALLATION.
- 3. POOL DECK INSTALLATION.
- 4. SHADE STRUCTURE INSTALLED ON DRIVEWAY.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE16110266 CASE ADDR: 457 SW 28 AV

OWNER: HYPPOLITE, SANDRA INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SHED BUILT IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE11040091
CASE ADDR: 509 NW 20 AV

OWNER: RETLEY, LELA EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR

INSPECTIONS:

- 1. MOST OF THE WINDOWS AT THE DWELLING WERE REPLACED.
- AN EXTERIOR DOOR WAS REPLACED AT THE REAR OF THE PROPERTY

# FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE FAUCET FOR THE TUB, THE LAVATORY AND VANITY, AND THE TOILET WERE REPLACED IN THE BATHROOM.

### FBC(2007) 1612.1.2

ALL THE WINDOWS, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

# FBC(2007) 1626.1

THE WINDOWS AND DOORS THAT HAVE BEEN INSTALLED DO NOT PROVIDE THE REQUIRED RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS. AN APPROVED SHUTTER SYSTEM

HAS NOT BEEN PROVIDED.

CASE NO: CE15092413 CASE ADDR: 1536 NW 5 AV

OWNER: MERCADO, REINALDO J

PEREZ, KARAMANOGLU

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. EXTENSIVE REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS MAY BE CITED IF DISCOVERED DURING THE CONSTRUCTION PROCESS. THIS INCLUDES STRUCTURAL ALTERATIONS MADE TO THE ROOF AND WALL STRUCTURE OF THE BUILDING.

### FBC(2014) 105.3.1.4.10

THE FOLLOWING WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFED THE STRUCTURE PRIOR TO OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE REPLACEMENT OF THE EVAPORATOR UNIT, THERMOSTAT, THE CONDENSER UNIT, ALL REGISTERS AND ELECTRICAL CIRCUITS.

# FBC(2014) 105.3.1.4.3

THE FOLLOWING WORK REQUIRES A DEMOLITION PERMIT AND INSPECTIONS:

1. COMPLETE INTERIOR DEMOLITION HAS BEEN PERFORMED PRIOR TO OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. PLUMBING ALTERATIONS, MODIFICATIONS, HAVE COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS. THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE DISPOSAL, IRRIGATION AND R & R SINKS/WATER BASINS.

### FBC(2014) 105.3.1.4.5

THE FOLLOWING WORK REQUIRES AN ELECRICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, RE-WIRING, WALL OUTLETS, SWITCHES, A/C SUPPLY AND METER BASE.

### FBC(2014) 107.1.1

SUBMITTAL OF 2 SETS OF PLANS AND SPECIFICATIONS AS OUTLINED IN THIS SECTION OF THE FLORIDA BUILDING CODE.

#### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF \$500 PER DAY FOR VIOLATIONS OF THIS SECTION OF THE FLORIDA BUILDING CODE.

#### FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED.

WORK WITHOUT PERMITS DEEMED THIS BUILDING AS UNSAFE AND SUBJECT TO BOARD-UP AND/OR DEMOLITION UNDER THE SECTION OF THIS CODE.

\_\_\_\_\_\_

CASE NO: CE15101560
CASE ADDR: 3121 SW 20 CT
OWNER: BARNETTE, KYLE W

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEMOLITION OF ROOF.

### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. WATER HEATER MANUFACTURED IN JANUARY/2010 INSTALLED.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. ELECTRICAL FOR WATER HEATER.

### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

# FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

------

CASE NO: CE15120733

CASE ADDR: 1017 E LAS OLAS BLVD
OWNER: PRESTONS HOLDING LAND TR

ULMER, JAMES I TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MEZZANINE/ATTIC PLATFORM BUILT OVER MEN'S ROOM.
NOT PERMITED PLANS. AREA BEING USED AS STORAGE AND
MAKESHIFT OFFICE. NO ENGINEERING TO DETERMINE IF
RATED FOR LOAD.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15121156
CASE ADDR: 1115 NE 6 AV
OWNER: JONES, GLORIA M

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THIS DWELLING HAS BEEN DAMAGED BY FIRE. FIRE RESTORATION HAS BEEN DONE WITHOUT PERMITS. CERTIFICATES FOR OCCUPANCY DEEMING THE STRUCTURE SAFE AFTER FIRE DAMAGE HAVE NOT BEEN ISSUED.

### FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. FIRE RESTORATION.
- 2. STORM SHUTTER INSTALLATION.
- 3. REPAIRING OF SMOKE AND FIRE DAMAGED INTERIOR WALLS.
- 4. BUILT SHEDS WHICH ARE NOW IN THE SETBACK.
- 5. PERMITS WERE ALLOWED TO EXPIRE AND WORK IS NOW WORK WITHOUT PERMIT.

# FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. REPLACED FIRE DAMAGED DUCT WORK.
- 2. NEW SPLIT SYSTEM EQUIPENT REPLACED.
- 3. PERMIT EXPIRED BECOMING WORK WITHOUT PERMIT.

### FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACEMENT OF PLUMBING FIXTURES.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMITS.

#### FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL REPAIRS DUE TO FIRE DAMAGE.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMIT.

FBC(2014) 105.3.2.1

JONES, GLORIA

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE: 99070788 Expired BSHUTTERST 1115 NE 06 AVJONES, GLORIA M STORM SHUTTERS

11120763 Expired BALTR1M 1115 NE 6 AV JONES, GLORIA M SFR REPLACE SMOKE DAMAGED DRYWALL 1000 SQ FT

11120767 Expired MDUCT 1115 NE 6 AV

M REPLACE DUCTS BP 11120763

JONES, GLORIA M ELECTRIC FOR REPAIR SMOKE DAMAGE BP 11120763

11120771 Expired PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M REPLACE FIXTURES BP 11120763

JONES, GLORIA M ATF ELECTRICAL AS PER PLAN BP14120081

14120081 Expired BALTR1M 1115 NE 6 AV JONES, GLORIA M ATF REPAIR FIRE DAMAGE

14120101 Expired PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M ATF REPLACE FIXTURES BP14120081

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 116.1.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS AND INSPECTED:

WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15121310

CASE ADDR: 4100 N FEDERAL HWY
OWNER: 4100 FEDERAL HWY LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN LAYOUT RECONFIGURED FROM ORIGINAL FLOORPLAN.
- 2. DINING ROOM LAYOUT CHANGED.
- 3. INSTALLED CANOPY ON NORTH SIDE OF BUILDING.
- 4. RECONFIGURED STORAGE AREAS.
- 5. BUILT A DECORATIVE STRUCTURE WITHIN THE DINING/BAR AREA.
- 6. 3 SIGNS INSTALLED USING THE EXISTING ELECTRICAL.

### FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMOVED BAR AREA AND SINKS.
- 2. REMOVED WALL SINKS AT ENTRY TO KITCHEN.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW PLUMBING AND FIXTURES. PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW PLUMBING ALTERATIONS.

#### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW ELECTRICAL. NEW CONDUITS VISIBLE.
PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW
ELECTRICAL INSTALLATIONS. ELECTRICAL ALTERATIONS
TO THE BAR AREA.

#### FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. STORAGE FREEZERS HAVE BEEN ALTERED.
- 2. NEW MECHANICAL INSTALLATION UNDER CANOPY ON NORTH SIDE OF BUILDING.

### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF EXTERIOR DOORS AT NORTH SIDE OF BUILDING.

#### FBC(2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS FROM A CERTIFIED AND LICENSED DESIGN PROFESSIONAL ADDRESSING THE ENTIRE EXISTING STRUCTURE AND SYSTEMS.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16021515
CASE ADDR: 2961 SW 19 AVE
OWNER: KEYSTONE HALLS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. COMPLETE DEMOLITION OF THE STRUCTURE.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.\_\_\_\_\_

CASE NO: CE16030296
CASE ADDR: 2370 NW 26 ST
OWNER: BENJAMIN, ERNST

BENJAMIN, ROSE MARIE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACED ROOF DECKING WITH STRIPS OF 5 INCH PLYWOOD.
- 2. MODIFIED ROOF RAFTERS BY SCABBING PIECES OF WOOD
- 3. STRUCTURAL REPAIRS TO ROOF STRUCTURE REQUIRING ENGINEERING.
- 4. CEILING DRYWALL COVER HAS BEEN REPLACED THROUGHOUT THE HOUSE.

#### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

# FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16041244
CASE ADDR: 415 NW 7 ST

OWNER: TRUST NO 413-415

LAND TRUST SERVICE CORP TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. INSTALLED FENCE ON PERIMETER OF PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16041787
CASE ADDR: 508 NW 15 AV
OWNER: CHIWARA, GRACE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURE HAS BEEN ALTERED TO CREATE UTILITY CLOSET. (COMPLIED)
- 2. ALTERED INTERIOR WALL TO CONVERT TO DUPLEX. (COMPLIED)
- 3. ADDED KITCHEN FOR SECOND APARTMENT UNIT. (COMPLIED)
- 4. ADDED BATHROOM FOR SECOND APARTMENT UNIT.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED SPLIT A/C MECHANICAL SYSTEM WHICH INCLUDES CONDENSER UNIT AND EVAPORATOR UNIT. (EQUIPMENT REMOVED, COMPLIED)
- 2. INSTALLED DUCT WORK FOR CENTRAL A/C MECHANICAL SYSTEM.

# FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED WINDOWS AND DOORS. NOT RELATED TO WINDOW ATF WINDOW PERMIT 15072197. (ISSUED PERMIT 16072392 FOR 7 WINDOWS.)

#### FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLED FENCE IN BACK YARD. (COMPLIED)

### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLED PVC WASTE LINES IN KITCHEN.
- 3. INSTALLED PVC WASTE LINES ON EXTERIOR CONNECTED TO SANITARY SEWER SYSTEM.
- 4. INSTALLED WATER HEATER. HOT WATER SIDE IS PVC.
- 5. TPR VALVE MISSING EXTENSION.

#### FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- INSTALLED WIRING FOR CENTRAL A/C SYSTEM. (COMPLIED, REMOVED)
- INSTALLED WIRING CIRCUITS IN CARPORT. (COMPLIED, REMOVED)
- 3. INSTALLED WIRING CIRCUITS FOR WATER HEATER. (COMPLIED, REMOVED)
- 4. REPLACED BREAKER PANEL.

#### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO A DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT. (COMPLIED)

### NEC(2005) 408.38

ELECTRICAL BOXES MISSING COVER EXPOSING ENERGIZED ELECTRICAL CONNECTIONS.

NEC(2005) 110.27

ALL OUTLETS AND SWITCHES MUST HAVE COVERS AS TO NOT EXPOSE ENERGIZED ELECTRICAL CONNECTIONS.

-----

CASE NO: CE16050163 CASE ADDR: 1533 NW 19 AVE

OWNER: DRAGOSLAVIC, SLAVOLJUB & MARA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT CARPORT. (COMPLIED)
- 2. BUILT FRONT PORCH. (COMPLIED)
- 3. BUILT ADDITION.
- 4. INSTALLED INTERIOR DROP CEILING. (COMPLIED)

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED ARCHITECTURAL SHINGLE ROOF. (COMPLIED)

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED A SPLIT AIR CONDITIONING SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED PLUMBING FIXTURES AND ALTERED THE PLUMBING SYSTEM SO THAT SEWAGE IS BACKING UP AT THE CLEANOUT BY THE SIDEWALK. (COMPLIED)

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED ELECTRICAL FIXTURES AND WIRING ABOVE THE DROP CEILING.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

### FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. DUE TO A FIRE THE STRUCTURE IS NOW DEEMED UNSAFE BY THE CITY. (COMPLIED)

.-----

CASE NO: CE16050226

CASE ADDR: 728 NW 6 AVE # A OWNER: CASALE, ROSANNE D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

 FRAMED AND INSTALLED DRYWALL ON OFFICE ENCLOSURE IN THIS WAREHOUSE.
 NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

INSTALLED SPLIT A/C MECHANICAL SYSTEM.
 NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK
 DONE.

# FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED NEW ELECTRICAL CIRCUITRY AND FIXTURES, INCLUDING LOW VOLTAGE CIRCUITS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050886 CASE ADDR: 1433 NW 3 AV

OWNER: HIZUENGA 1433 LAND TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. STRUCTURAL WORK IN PROGRESS ON EXTERIOR OF BUILDING.
- 2. INTERIORS WALLS HAVE BEEN REMOVED.
- 3. STRUCTURAL OPENINGS AROUND WINDOWS HAVE BEEN MODIFIED.
- 4. WALLS IN BATHROOM HAVE BEEN OPENED AND COVERED WITH DURA-ROC.

#### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. WINDOWS AND DOORS HAVE BEEN INSTALLED.

### FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. GATES AND FENCE HAVE BEEN INSTALLED.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. CHANGING AND INSTALLING NEW PLUMBING FIXTURES IN KITCHEN AND BATHROOMS.

#### FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACING ELECTRICAL FIXTURES, SWITCHES AND OUTLETS.
- 2. REWIRING FOR ELECTRICAL FIXTURE REPLACEMENT.
- 3. REWIRING AND RECONFIGURING BREAKER PANEL.
- 4. REWIRING FOR ELECTRICAL FIXTURE REPLACEMENT.

### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

FBC(2014) 115.1

A STOP WORK ORDER WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

\_\_\_\_\_\_

CASE NO: CE16051413 CASE ADDR: 2009 SE 24 AV

OWNER: HUDSON, DARYL PAUL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACING ONSITE DRIVEWAY.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION OF IMPACT WINDOWS AND DOORS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16051422

CASE ADDR: 1249 SEABREEZE BLVD

OWNER: MITTONE, HUGO F

MITTONE, PATRICIA N

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 2. TILED WALL COVERINGS IN BATHROOMS AND KITCHENS INCLUDING BUT NOT LIMITED TO WET AREAS.

#### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK AND REGISTERS.

#### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT OF DOORS AND WINDOWS.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER SUPPLY AND WASTE LINES.
- 2. INSTALLATION OF BATHROOM AND KITCHEN FIXTURES NOT LIMITED TO SINKS, FAUCETS, VANITIES, TOILETS AND BIDETS.
- 3. INSTALLATION OF WATER HEATER.

## FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS.
- 2. INSTALLATION OF ELECTRICAL FIXTURES.
- 3. INSTALLATION OF BREAKER PANELS.
- 4. INSTALLATION OF NEW LIGHTING.
- 5. INSTALLATION OF NEW RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4

(D) (1) THRU (D) (6)

GFI'S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

#### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

#### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

------

CASE NO: CE16061695 CASE ADDR: 1206 NW 11 PL

OWNER: DRAGOSLAVIC, SLAVOLJUB & MARA

INSPECTOR: JOSE ABIN

#### VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODEL INCLUDING BATHROOM WET AREA.

### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW FIXTURES IN BATHROOMS AND KITCHEN.
- 2. WATER HEATER.

## FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF FIXTURES INCLUDING ELECTRICAL PANEL.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:
WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A
PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL
BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED
FOR NEW DWELLINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

-----

CASE NO: CE16061719 CASE ADDR: 1736 NW 18 ST

OWNER: PRIME PROSPECT PROPERTIES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING INCLUDING BATHROOM WET AREAS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW WATER SUPPLY LINES.
- 2. INSTALLATION OF NEW WASTE LINES.
- 3. INSTALLATION OF NEW FIXTURES.
- 4. INSTALLATION OF TANKLESS WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW BREAKER PANEL.
- 2. INSTALLATION OF NEW WIRING CIRCUITS.
- 3. INSTALLATION OF NEW FIXTURES.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF NEW MECHANICAL SPLIT A/C SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

\_\_\_\_\_\_

CASE NO: CE16062114 CASE ADDR: 3316 NE 18 ST

OWNER: WILLIAMS, GERARD S & JULIE C

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THE FOLLOWING DESCRIBED WORK REQUIRES A DEMOLITION

PERMIT AND INSPECTIONS:

1. INTERIOR DEMOLITION INCLUDING BUILDING, MECHANICAL, ELECTRICAL AND PLUMBING.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY
REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND
ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION
OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16071180
CASE ADDR: 512 NW 15 TER
OWNER: PASCAL 2014 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

THE FOLLOWING MANNER, BUT NOT LIMITED TO.

- 1. THE INTERIOR FLOOR PLAN CONFIGURATION OF THIS SINGLE FAMILY HOME HAS BEEN ALTERED.
- 2. KITCHEN HAS BEEN REMODELED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. BATHROOM HAS BEEN ADDED.
- 5. FRONT PORCH HAS BEEN BUILT AND ENCLOSED.
- 6. SECOND ACCESSORY STRUCTURE HAS BEEN BUILT AT BACK OF PARCEL AND CONVERTED TO A SECOND OCCUPIED RESIDENCE.
- 7. UTILITY LAUNDRY CLOSET BUILT AT BACK OF PRIMARY STRUCTURE.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLATION OF WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM ADDED, BATHROOM REMODEL LAUNDRY AND WATER HEATER.
- 3. INSTALLATION OF WATER HEATER.

#### FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS TO SERVICE WATER HEATER, WASHER-DRYER, MECHANICAL SYSTEM, RECEPTACLES AND FIXTURES.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF BREAKER PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

## FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

.\_\_\_\_\_

CASE NO: CE16081196
CASE ADDR: 2642 BARBARA DR

OWNER: M100 HOLDINGS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONSTRUCTING FACADE OF 26 GAUGE STEEL AT FRONT ELEVATION. (COMPLIED)
- 2. KITCHEN AND BATH REMODEL WITH AN APPLIED FOR PERMIT. PERMIT WAS NOT ISSUED. (COMPLIED)

STOP WORK ORDER POSTED.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFING OF THE STRUCTURE.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- INSTALLATION OF DOORS WITH AN APPLIED FOR PERMIT. (COMPLIED)
- 2. REMOVAL OF ACCORDION SHUTTERS AND INSTALLATION OF WINDOWS. (COMPIED)

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLATION OF PLUMBING FIXTURES FOR KITCHEN AND BATH REMODEL. (COMPIED)

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF ELECTRICAL FIXTURES AND OUTLETS FOR KITCHEN AND BATH REMODEL. (COMPLIED)

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6).
GFIS REQUIRED AS PER NEC 108.8.
OUTLET SPACING AS REQUIRED UNDER NEC 210.52.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

## FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16081266 CASE ADDR: 1544 NW 15 TER

OWNER: WRIGHT, ELIZABETH C &

WRIGHT, JONATHAN

INSPECTOR: JOSE ABIN

## VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NO PERMIT FOR BACKYARD STRUCTURE. NOW OCCUPIED AS LIVING SPACE.
- 2. REMODELED KITCHEN AND BATHROOM INCLUDING TILE BACKER IN WET AREAS.
- 3. ADDED 2 KITCHENS. ONE IN THE CONVERTED CARPORT AND THE OTHER IN THE BACKYARD STRUCTURE.
- 4. ALTERED THE INTERIOR FLOOR PLAN OF MAIN RESIDENCE.

## FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED PLUMBING FIXTURES IN BATHROOM AND KITCHEN.
- 2. PLUMBING FOR 2 ADDED BATHROOMS AND KITCHENS.

### FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED NEW CIRCUITS FOR A/C SYSTEM.
- 2. INSTALLED NEW LIGHTING FIXTURES AND CIRCUITS.
- 3. INSTALLED NEW OUTLETS IN KITCHEN.
- 4. INSTALLED ELECTRICAL PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6) GFI?S REQUIRED AS PER NEC 108.8 OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED A SPLIT MECHANICAL A/C SYSTEM.

### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED DOORS AND WINDOWS.

#### FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

## FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO THAT OF 3-FAMILY SERVED BY A SINGLE ELECTRICAL METER WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

\_\_\_\_\_\_

CASE NO: CE16090428 CASE ADDR: 1408 NW 3 AVE

OWNER: CR INVESTMENTS SOLUTION LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING, INCLUDING REPLACEMENT OF TILE-BACKER IN WET AREAS.
- 2. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 3. CMU BLOCK OVER EXISTING OPENINGS ON EXTERIOR WALLS.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN BATHROOM AND KITCHEN.
- 2. INSTALLATION OF TANKLESS WATER-HEATER.
- 3. INSTALLATION OF WATER SUPPLY LINES AND WASTE LINES.

INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

## FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:
INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEMS.

## FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION OF WINDOWS AND DOORS.

### FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF NEW FENCING.

#### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

#### FBC(2014) 115.1

A STOP WORK ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

------

CASE NO: CE16091372
CASE ADDR: 520 NW 23 AVE
OWNER: YAFLAG LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CLOSED EXTERIOR DOOR OPENING AT KITCHEN.

#### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. REPLACED WINDOWS.

## FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. REPLACEMENT OF ELECTRICAL PANEL AND OUTLETS.

## FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16101307
CASE ADDR: 600 NW 18 ST
OWNER: KAAREFL CORP
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 1029.4

THIS BUILDING HAS BEEN ILLEGALLY ALTERED FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. PLACED SHUTTERS AND WOOD PANELS ON A PERMANENT BASIS OVER WINDOWS.
- 2. PERMANETLY SCREWED SHUT WINDOW.

#### FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT A SCREEN ENCLOSURE ON THE RIGHT ELEVATION.
- 2. BUILT INTERIOR PARTITIONS TO DIVIDE THE EAST APARTMENT INTO 2 UNITS.
- 3. ADDED 2 BATHROOMS IN UTILITY ROOMS OF EACH UNIT.
- 4. ADDED KITCHEN AT EAST SIDE UNIT.
- 5. BLOCKED WINDOWS WITH WOOD PANELS AT SEVERAL LOCATIONS OBSTRUCTING EMERGENCY ESCAPE.
- 6. SCREWED SHUT A WINDOW OBSTRUCTING EMERGENCY ESCAPE.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED WATER HEATER.
- 2. PLUMBING FOR 2 ILLEGALLY ADDED BATHROOMS.
- 3. PLUMBING FOR CLOTHES WASHER.
- 4. PLUMBING FOR ILLEGALLY ADDED KITCHEN.

## FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. CIRCUITS ADDED TO SERVICE CLOTHES DRYER.
- 2. CIRCUIT ADDED TO SERVICE CLOTHES WASHER.
- 3. CIRCUITS ADDED TO SERVICE WATER HEATER.
- 4. CIRCUITS ADDED TO SERVICE 2 AIR CONDITIONERS.
- 5. CIRCUIT ADDED TO SERVICE ILLEGAL KITCHEN.

### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF 2 MECHANICAL SPLIT A/C SYSTEMS. SYSTEM NUMBER 1 DATED 2004. SYSTEM NUMBER 2 DATED 2016.
- 2. INSTALLED DUCT WORK TO SERVICE THE 2 A/C SYSTEMS.
- 3. THIRD ILLEGAL UNIT DOES NOT HAVE THERMOSTAT.

#### FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED WINDOW AT BATHROOM OF UNIT W.

## FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLED WOOD FENCE AND THE PERMIT WAS VOIDED.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

## FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. EAST UNIT WAS CONVERTED INTO 2 APARTMENTS.

## NEC(2005) 110.12

OPEN PORT AT ELECTRICAL CIRCUIT PANEL.

## NEC(2005) 110.27

- (A) LIVE PARTS GUARDED AGAINST ACCIDENTAL CONTACT. EXCEPT AS ELSEWHERE REQUIRED OR PERMITTED BY THIS CODE, LIVE PARTS OF ELECTRICAL EQUIPMENT OPERATING AT 50 VOLTS OR MORE SHALL BE GUARDED AGAINST ACCIDENTAL CONTACT BY APPROVED ENCLOSURES OR BY ANY OF THE FOLLOWING MEANS:
- 1. BY LOCATION IN A ROOM, VAULT, OR SIMILAR ENCLOSURE THAT IS ACCESSIBLE ONLY TO QUALIFIED PERSONS.
- 2. ELECTRICAL PANEL LOCATED IN ILLEGAL BATHROOM OVER TOILET BOWL.

------

CASE NO: CE16101554
CASE ADDR: 724 NW 17 ST

OWNER: SHUTTS, JASON ALBERT

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND

WINDOW PERMIT AND INSPECTIONS:

1. REMOVED WINDOW AND INSTALLED DOOR AT RIGHT ELEVATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16101768
CASE ADDR: 1700 NW 26 AVE

OWNER: FREEDOM MORTGAGE CORP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM REMODEL.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. PLUMBING FIXTURES IN KITCHEN AND BATHROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF METER BASE.
- 2. REPLACEMENT OF MAIN DISCONNECT PANEL.
- 3. INSTALLATION OF RECEPTACLES.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. THE SLOPED PORTION OF THE ROOF WAS REPLACED IN 2009.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF MECHANICAL CENTRAL A/C SYSTEM.
- 2. INSTALLTION OF DUCT WORK.

## FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16121633 CASE ADDR: 2201 NE 16 ST EDWARDS, RANDY L OWNER: INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY AND CONCRETE GARDEN WALLS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121682 CASE ADDR: 1521 SW 4 AVE WILLIAMS, JOSIE OWNER: INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

1. NEW PAVER DRIVEWAY INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16020537 CASE ADDR: 5570 NW 10 TER

OWNER: 5551 NW 9TH AVE 1-5 LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THERE HAS BEEN A COMPLETE DEMOLITION OF THE 5112 SQ.FT.

STRUCTURE LOCATED ON THIS PROPERTY WITHOUT

OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

REQUIRED INSPECTIONS HAVE NOT BEEN DONE.

\_\_\_\_\_\_

CASE NO: CE16041977
CASE ADDR: 1511 NW 11 PL

OWNER: 2771 LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THE STRUCTURES ON THIS PROPERTY HAVE BEEN ALTERED WITHOUT PERMIT IN THE FOLLOWING MANNER:

- 1. WINDOWS AND EXTERIOR DOORS HAVE BEEN REPLACED.
- 2. GLASS BLOCK HAS BEEN INSTALLED IN PLACE OF THE BATHROOM WINDOW.
- 3. NEW SINK AND TOILET INSTALLED IN THE BATHROOM.
- 4. THE KITCHEN HAS BEEN REMODELED WITH ELECTRICAL OUTLETS AND DISHWASHER ADDED. KITCHEN SINK REPLACED.
- 5. THE WATER HEATER HAS BEEN REPLACED.
- 6. PLUMBING AND ELECTRICAL HAS BEEN ADDED FOR A WASHER AND DRYER IN THE UTILITY ROOM.
- 7. A CENTRAL A/C SYSTEM HAS BEEN INSTALLED.
- 8. ELECTRICAL SERVICE HAS BEEN UPGRADED WITH AN OUTSIDE BREAKER PANEL.
- 9. THE SHED DOOR HAS BEEN REPLACED.
- 10. A WOOD FENCE IS INSTALLED ON THE WEST SIDE OF THE HOUSE.

-----

CASE NO: CE16080203

CASE ADDR: 2520 YACHT CLUB BLVD OWNER: DAVID NEAL COOPER TR

COOPER, DAVID NEAL TRSTEE ETAL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLACED GRAVEL IN THE SWALE WITHOUT THE REQUIRED APPROVAL FROM ENGINEERING.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. NEW FENCE AND GATES INSTALLED ON BOTH SIDES OF FRONT ELEVATION.

FBC(2014) 105.3.1.4.8

THE FOLLOWING DESCRIBED WORK REQUIRES A PERMIT AND INSPECTIONS:

1. NEW COVERED PERGOLA INSTALLED IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16090315 CASE ADDR: 2300 NW 6 ST OWNER: RSKYR LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER, BUT NOT LIMITED TO:

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT

LIMITED TO:

PLUMBING ALTERATIONS, MODIFICATIONS, HAVE
COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS.
THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE
DISPOSAL AND IRRIGATION.
ALL PLUMBING ALTERATIONS MODIFICATIONS AND REPAIRS
UNDER THE SECTION OF THIS CODE.
THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING
PERMIT AND INSPECTIONS:
1. NEW SEWER PIPE INSTALLED CONNECTING THE CLEAN OUT.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16090939
CASE ADDR: 1135 NE 11 AV
OWNER: SCHNEIDER, RUSSELL
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NO PERMITS ON ADDITIONS AND REMODELING.
- 2. ADDITION AND ROOFING INSTALLED ON BACK OF HOUSE. NO PERMITS.
- 3. FLAT ROOF HAS FRAMING WITH MESH SET UP ON OUTSIDE OF HOUSE ROOF.
- 4. NEW WINDOWS AND DOORS INSTALLED ON ENTIRE HOUSE. LEFT SIDE HOUSE DOORS AND WINDOWS REMOVED AND CONCRETE BLOCK INSTALLED. NO PERMITS.
- 5. FENCING TRELLIS ON INSIDE OF PROPERTY. LEFT AND RIGHT SIDE OF HOUSE HIGHER THEN CODE. VISIBLE FROM ROAD.
- 6. ENTIRE HOUSE REMODELED. KITCHEN & 2 BATHROOMS AND WALLS MOVED WITH PLUMBING UPGRADES.
- 7. FLORIDA ROOM ENCLOSED TO BEDROOM. NO PERMITS.
- 8. FULL ELECTRICAL UPGRADE ON INSIDE. NO PERMITS.

\_\_\_\_\_\_

CASE NO: CE16091127
CASE ADDR: 1531 SW 26 ST
OWNER: SKY MOTEL INC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED:

1. BATHROOM REMODELED IN ROOM #37.

2. WINDOW OPENING CLOSED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. WINDOW OPENING CLOSED.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED TO THE PLUMBING SYSTEM.

1. NEW VANITY AND FAUCETS INSTALLED

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16091837 CASE ADDR: 2675 SW 13 ST

OWNER: LONE PALM PROPERTIES LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

- 1. BACK PORCH ENCLOSURE.
- 2. NEW DOORS AND WINDOWS.
- 3. NEW ELECTRICAL WIRING.

#### FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BACK PORCH ENCLOSED.

### FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW ELECTRICAL WIRING FOR BACK PORCH ENCLOSURE.

## FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW EXTERIOR DOORS AND WINDOWS INSTALLED ON BACK PORCH ENCLOSURE.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16101151 CASE ADDR: 2115 SE 18 ST

OWNER: BOAT HOUSE POOL INC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

1. NEW DOCK INSTALLED.

FBC(2014) 105.3.1.4.1

THE ERECTION OR CONSTRUCTION OF ANY BUILDING OR STRUCTURE, THE ADDING TO, ENLARGING, REPAIRING, IMPROVING, ALTERING, COVERING OR EXTENDING OF ANY

BUILDING OR STRUCTURE.
1. NEW DOCK INSTALLED

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16111320 CASE ADDR: 323 MOLA AV

OWNER: ASHITA HOMESTEAD LLC INSPECTOR: MARIO CARRASOUEL

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW FRENCH DOORS INSTALLED ON WEST AND NORTH

ELEVATIONS.
1. NEW METAL FRAME ROOF INSTALLED ON NORTH

FBC(2014) 105.3.1.4.10

ELEVATION.

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. NEW METAL FRAME ROOF INSTALLED NORTH ELEVATION.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. NEW FRENCH DOORS INSTALLED NORTH AND WEST ELEVATIONS.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16111516

CASE ADDR: 2437 GULFSTREAM LN
OWNER: NAGEN, MARY ELENA
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

- 1. PLUMBING PIPES INSTALLED FOR POOL ON SOUTH SIDE OF PROPERTY.
- 2. NEW BRICK PATIO AROUND THE POOL.

### FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW BRICK PATIO INSTALLED AROUND THE POOL.
- 2. DEMOLISHED AND CONSTRUCTED A NEW ASPHALT DRIVEWAY.
- 3. DEMOLISHED EXTERIOR PERGOLA STRUCTURE.

#### FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. NEW PLUMBING PIPES AND CONNECTIONS FOR THE POOL ON SOUTH SIDE OF THE PROPERTY.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16120177
CASE ADDR: 210 NURMI DR
OWNER: NURMI HOUSE LLC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. SMOKE/CARBON MONOXIDE DETECTOR INSTALLED.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN

ELECTRICAL PERMIT AND INSPECTIONS:

1. SMOKE/CARBON MONOXIDE DETECTORS SYSTEM

INSTALLED.

-----

CASE NO: CE16120882

CASE ADDR: 616 INTRACOASTAL DR

OWNER: 616 INTRACOASTAL DRIVE LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW WOOD FENCE INSTALLED UNDER PERMIT 1609052

FOR A TEMPORARY CONSTRUCTION FENCE.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. NEW WOOD FENCE INSTALLED UNDER THE WRONG PERMIT

BLOCKING WATER METERS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_

CASE NO: CE14111609

CASE ADDR: 545 S FTL BEACH BLVD 1101

OWNER: BRENNAN, MICHAEL INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION OF THE FRAMING AND DRYWALL THROUGHOUT THE KITCHEN, BATHROOMS, AND OTHER AREAS OF THIS UNIT WITHOUT THE REQUIRED DEMOLITION PERMITS AND/OR INSPECTIONS.

FBC (2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE ALTERATION OF ELECTRICAL WIRING AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT ALL REQUIRED PERMITS ARE OBTAINED, INSPECTED, PASSED AND CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE IN THIS CONDO BUILDING.

\_\_\_\_\_

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15061470
CASE ADDR: 1638 RIVER LN
OWNER: EVANS, JOHN
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING BEING DONE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

## FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_

CASE NO: CE15081042

CASE ADDR: 441 S FTL BEACH BLVD OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. THE COMPLETE BUILD-OUT OF A RESTAURANT.
- 2. NEW WINDOWS AND DOORS.
- 3. INTERIOR ALTERATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.11

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH MECHANICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. NEW A/C MECHANICAL UNITS AND DUCT WORK INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.4

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH PLUMBING ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.5

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH ELECTRICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. ALARM CONTROL PANEL.
- 2. LIGHTING.
- 3. ELECTRICAL CONDUIT, ELECTRICAL DISCONNECTS, LOW VOLTAGE INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC (2014) 107.1.1

THIS CODE CASE AND THE WORK DONE IN THIS COMMERCIAL BUILDING SPACE WILL REQUIRE ARCHITECTURAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO INCLUDE ALL OF THE VIOLATIONS THAT NEED TO BE PROPERLY PERMITTED, CORRECTED AND INSPECTED AS REQUIRED BY THE FLORIDA BUILDING CODE.

#### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

------

CASE NO: CE15091850

CASE ADDR: 200 S BIRCH RD # 1011 OWNER: FRENI MEHTA REV TR

MEHTA, FRENI TRSTEE

INSPECTOR: BOBBY MASULA

## VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. FULL KITCHEN REMODEL TO INCLUDE THE FRAMING DOWN OF THE KITCHEN CEILING AND INSTALLING DRYWALL.
- 3. FULL BATHROOM RENOVATION WITH INSTALLATION OF DRYWALL/TILE BACKING BOARD.

  THIS WORK HAS BEEN PERFORMED WITHOUT HE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE PLUMBING SYSTEM WHICH INCLUDE BUT IS NOT LIMITED TO:

- 1. INSTALLED A TANKLESS WATER HEATER.
- 2. CONVERTED THE TUB INTO A SHOWER.
- 3. REPLACED THE SHOWER VALVE.

4. REMOVED AND REPLACED ALL THE PLUMBING FIXTURES IN BOTH THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE ELECTRICAL SYSTEM WHICH INCLUDES BUT IS NOT LIMITED TO:

1. WIRING, OUTLETS, SWITCHES, DEVICES AND THE WIRING OF A TANKLESS WATER HEATER.

## FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS CONDO UNIT AND THE CONDO BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATIONS AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY QUADRUPLE FEES THAT WILL BE APPLY.

## FBC(2014) 110.6

SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED.

-----

CASE NO: CE15101220 CASE ADDR: 1230 NW 7 AV

OWNER: GALA INVESTMENTS GROUP LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. A COMPLETE INTERIOR REMODELING OF THE KITCHEN AND BATHROOM.
- 2. THERE IS A SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED IN THIS HOUSE AND WAS NEVER PERMITTED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC (2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM WAS ADDED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ELECTRICAL BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM ILLEGALLY ADDED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM INCLUDING THE DUCT WORK BEING REMOVED AND REPLACED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

## FBC(2014) 107.1.1

THIS PROPERTY AND CODE CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO ADDRESS AND PERMIT THE SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

## FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15110968

CASE ADDR: 3821 N OCEAN BLVD OWNER: MY FL 3821 LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ROOM REMODELING INCLUDING FRAMING, DRYWALL, INTERIOR WALL BOARD CLADDING, WOOD PLATFORM DECK INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING FIXTURES ARE BEING REMOVED AND REPLACED.
- 2. THERE ARE ROOMS WHERE A KITCHENETTE WAS REMOVED, A WOOD PLATFORM DECK BUILT AND JACUZZI TUBS INSTALLED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL DEVICES BEING REMOVED AND REPLACED, ELECTRICAL WIRING BEING INSTALLED OR ALTERED TO ACCOMMODATE NEW ELECTRICAL FIXTURES AND LOW VOLTAGE LIGHTING INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 107.1.1

BECAUSE OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE, THE POTENTIAL LIABILITY TO THIS HOTEL BUILDING AND OCCUPANTS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER THE FLORIDA BUILDING CODE.

## FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15120539

CASE ADDR: 3020 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL.
- 3. REBUILDING EXTERIOR STAIRS AND DECKS.
- 4. REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED. REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK IS BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK IS BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

## FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

## FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

## FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

## FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS MADE:
  - A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE:
  - A. ELECTRICAL PANELS REPLACED, DISCONNECTS
    INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES
    REMOVED, REPLACED OR RELOCATED WITHOUT THE
    REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

## FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

\_\_\_\_\_\_

CASE NO: CE16021361

CASE ADDR: 5321 NE 24 TER #107A

OWNER: NICOLAZZO, ELIZABETH & DOMINGO

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. THE COMPLETE REMODEL OF THE KITCHEN AND BATHROOMS WITH REMOVING AND REPLACING THE TILE BACKING BOARD WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.11

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL EXHAUST FANS BEING REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

#### FBC (2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.
- 2. A TANKLESS WATER HEATER HAS ALSO BEEN INSTALLED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH ROMEX WIRING, BLUE CUT IN BOXES, AND THE ELECTRICAL PANEL REPLACED AND OTHER ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING CONDO UNITS AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

## FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16031396

CASE ADDR: 2829 NE 30 ST # 205 OWNER: VAHER, ENNO & CARMEN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM BEING REMODELED WITHOUT THE REQUIRED PERMITS  $\mbox{\sc and/or}$ 

INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16050190
CASE ADDR: 2100 S OCEAN LN

OWNER: POINT OF AMERICA CONDO COMMON AREA

PHASE I & II

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

# FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

#### FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16050574

CASE ADDR: 2500 NE 48 LA # 509
OWNER: KEBE, STANLEY W
GOLDFIELD, SUZANNE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, REMODELING THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

### FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16071264 CASE ADDR: 2758 NE 15 ST

OWNER: CAMBRIDGE APARTMENTS E & W LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR AND EXTERIOR REMODELING INVOLVING STRUCTURAL, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

# FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

# FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16071518 CASE ADDR: 5405 NE 22 TER KNEZEVIC, ANA

KNEZEVICH, DAVID

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS AND REMODELING PERFORMED WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071960 CASE ADDR: 3086 HARBOR DR

RUSTLE INVESTMENTS LLC OWNER:

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS MADE SUCH AS BATHROOM REMODELING
- 2. REMOVED AND REPLACED DRYWALL/TILE BACK BOARD,
- 3. PLUMBING FIXTURES AND ELECTRICAL DEVICES REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080256 CASE ADDR: 2128 NE 63 ST

OWNER: REALTY FIRE IMPERIAL POINT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND RENOVATIONS INCLUDING STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

\_\_\_\_\_\_

CASE NO: CE16080753

CASE ADDR: 14 ISLA BAHIA DR OWNER: GROSVENOR, JUDSON

J MARK GROSVENOR TR ETAL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. EXTENSIVE ALTERATIONS MADE SUCH AS STEEL BEAMS INSTALLED, FRAMING, DRYWALL, A FULL INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

## FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE ELECTRICAL ALTERATIONS MADE WITHOUT THE REOUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND\OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY. BECAUSE OF THE SEVERITY OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE AND THE BLATANT ATTEMPT TO CIRCUMVENT THE REQUIREMENTS OF THE FLORIDA BUILDING CODE AND THE CITY OF FORT LAUDERDALE BUILDING DEPARTMENT THIS CODE CASE IS SUBJECT TO FOUR TIMES THE FEE ON ALL REQUIRED AFTER THE FACT PERMITS THAT WILL BE REQUIRED FOR COMPLIANCE FOR THIS CODE CASE.

### FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16090154

CASE ADDR: 1509 N FTL BEACH BLVD

OWNER: NUCCI, MARY J H/E

NUCCI, DANIELLE W

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF A CARPORT AND ROOF STRUCTURE

WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND

PAY DOUBLE PERMIT FEES THAT MAY APPLY.

\_\_\_\_\_

CASE NO: CE16101617

CASE ADDR: 2436 OKEECHOBEE LN

OWNER: FUNG YOUNG, RICARDO ALONSO

GLANERT, CLEONICE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. SWIMMING POOL AND POOL DECK BEING BUILT THAT ARE NOT IN ACCORDANCE WITH THE APPROVED PLANS. THE SCOPE OF WORK HAS EXCEEDED THE PREVIOUS APPROVED PLANS THAT WERE ISSUED.

2. THE MASTER POOL PERMIT 15111202 HAS NOW EXPIRED AND THE PERMIT IS NOW POTENTIALLY NULL AND VOID. THE POOL HAS NOT PASSED THE REQUIRED INSPECTIONS AND THE MAJORITY OF THE WORK IS COMPLETED, THE POOL IS FILLED AND BEING USED. THIS POOL IS NOW

CONSIDERED AN UNSAFE STRUCTURE AND POSES A POTENTIAL LIFE SAFETY ISSUE.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16110245

CASE ADDR: 2841 N OCEAN BLVD # 2007

OWNER: BEAULIEU, LISE

GOSSELIN, MARCEL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING WITH FRAMING, DRYWALL, PLUMBING AND ELECTRICAL WORK PERFORMED WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

# FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111690

CASE ADDR: 2841 N OCEAN BLVD # 1510

OWNER: AGUADO, JOHN

JOHN AGUADO REV LIV TR

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE TO THE PLUMBING WHICH HAS

COMPROMISED THE FIRE PENETRATIONS BETWEEN FLOORS.

THIS WORK WAS PERFORMED WITHOUT THE REQUIRED

PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16111730
CASE ADDR: 1779 SE 25 AV
OWNER: MIADO LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INTERIOR DEMOLITION OF THE KITCHEN,

BATHROOMS, INTERIOR WALLS AND A COMPLETE INTERIOR

RENOVATION IN PROGRESS INCLUDING STRUCTURAL, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED

PERMITS AND OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN

ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16120003

CASE ADDR: 350 E DAYTON CIR
OWNER: GARCIA, RICARDO
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ILLEGAL SUBDIVISION OF THE HOUSE AND CREATING THREE SEPARATE STUDIO LIVING UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THERE IS ALSO A FENCE ACROSS THE FRONT OF THE PROPERTY INSTALLED WITHOUT THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS

EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16121219
CASE ADDR: 2733 NE 25 PL
OWNER: MARTELLO, REGINA
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND ALTERATIONS OF INTERIOR WALLS, MECHANICAL, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

------

CASE NO: CE17010286

CASE ADDR: 2595 N FEDERAL HWY

OWNER: 3157 INC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK

BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND

POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

#### FBC(2014) 116.1.1

THIS PROPERTY WAS STRUCTURALLY DAMAGED AS THE RESULT OF A VEHICLE CRASHING INTO THE BUILDING AND COMPROMISING THE STRUCTURAL INTEGRITY OF THE BUILDING.

------

CASE NO: CE17030271 CASE ADDR: 837 NW 8 AVE

OWNER: WILLIAM F KEHRES REV TR

% GRANT W KEHRES

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS ELECTRICAL WORK,
OPENINGS BETWEEN THE BAYS BLOCKED IN AND AN
ILLEGAL SPRAY BOOTH INSTALLED AND BEING USED
WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, VIOLATIONS AS AN UN-SAFE STRUCTURE WITH SEVERITIES RELATED TO LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

# FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

### FBC (2014) 116.1.1

THIS PROPERTY HAS BEEN POSTED AS AN UNSAFE STRUCTURE AND CITED UNDER FBC 116 FOR THE FOLLOWING REASONS:

1. THIS BUSINESS IS PERFORMING ILLEGAL PAINTING OF VEHICLES WITHOUT THE PROPER EQUIPMENT AND SAFEGUARDS IN PLACE TO PROTECT THE BUSINESS, EMPLOYEES, THE ENVIRONMENT, AND THE NEIGHBORING PROPERTIES AND THE COMMUNITY. THE FACT THAT THIS ILLEGAL SPRAY BOOTH WAS NEVER PROPERLY PERMITTED AND/OR INSPECTED, THE BUSINESS IS OPERATING ILLEGALLY AND AS AN IMPROPER USE. THE REQUIRED PERMITS NEED TO BE OBTAINED TO BRING THE PROPERTY INTO COMPLIANCE FOR A SAFE OPERATION.

### FBC(2014) 116.2.1.1.2

THIS PROPERTY AND BUSINESS CURRENTLY HAS AN UNWARRANTED AMOUNT OF PAINT DUST WHICH IS FLAMMABLE, DEBRIS FROM VEHICLES AND OTHER COMBUSTIBLE MATERIAL THAT HAS ACCUMULATED OVER THE YEARS. THE BUSINESS APPEARS TO BE OPERATING MORE AS A JUNK YARD WITH VEHICLES AND PARTS THAT APPEAR TO HAVE BEEN ABANDONED OVER THE YEARS. THESE VIOLATIONS HAVE CREATED A FIRE HAZARD.

# FBC(2014) 116.2.1.1.3

THIS PROPERTY AND BUSINESS CURRENTLY HAS HAZARDS WITH RESPECT TO MEANS OF EGRESS DUE TO THE ACCUMULATION OF WHAT APPEARS TO BE ABANDONED VEHICLES AND A LARGE AMOUNT OF SCATTERED DEBRIS AND VEHICLE PARTS. IT ALSO APPEARS THAT A WALL HAS BEEN BLOCKED UP WHICH HAS ALTERED THE ORIGINAL FLOOR PLAN OF THIS BUILDING. THESE VIOLATIONS HAVE CREATED A HAZARD FOR EGRESS.

### FBC(2014) 116.2.1.2.5

THIS PROPERTY AND BUSINESS HAS MULTIPLE ELECTRICAL VIOLATIONS RELATED TO ELECTRICAL WORK WITHOUT PERMITS AND A LACK OF MAINTENANCE ON THE EXISTING ELECTRICAL PANEL AND EQUIPMENT THROUGHOUT THIS BUILDING.

### FBC(2014) 116.2.1.2.8

THIS PROPERTY HAS EXTENSIVE VIOLATIONS THAT ARE RELATED TO LIFE SAFETY ISSUES. UNTIL THIS PROPERTY AND BUSINESS COME INTO COMPLIANCE THE BUSINESS OPERATION IS IN VIOLATION OF THE USE OF THIS OCCUPANCY AND ITS BUSINESS OPERATIONS SHALL CEASE AND DESIST UNTIL ALL OF THE REQUIREMENTS FOR COMPLIANCE ARE MET.

\_\_\_\_\_\_

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE, CODE OF ORDINANCES

------

CASE NO: CE15102378

CASE ADDR: 680 TENNIS CLUB DR # 301

OWNER: LOPEZ, DENNIS R

LOPEZ, DENNIS A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. WORK WITHOUT PERMIT IN PROGRESS, THE INTERIOR OF THE UNIT WAS GUTTED WITHOUT A DEMOLITION PERMIT.
- 2. RENOVATIONS ARE BEING DONE AS FRAMING, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE PROPER PERMITS AND INSPECTIONS, INCLUDING THE OPENINGS ON THE FIRE PARTITONS.
- 3. WINDOWS WERE REPLACED.
- 4. CENTRAL A/C IS BEING REPLACED AND THE DUCT WORK IS BEING ALTERED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

------

CASE NO: CE15080754 CASE ADDR: 1706 NW 14 CT

OWNER: TYLER TUCHOW REV TR

TUCHOW, TYLER TRSTEE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. GARAGE WAS CONVERTED INTO LIVING SPACE.

- 2. CONSTRUCTION OF A SECOND BATHROOM.
- 3. AIR CONDITIONING SYSTEM CHANGE OUT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE16062033 CASE ADDR: 3130 NW 69 CT

OWNER: REYNA, KATHERINE M
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CENTRAL AIR CONDITIONER REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16040644

CASE ADDR: 325 ISLE OF CAPRI

OWNER: GALLUZZO, GEORGE R JR & MELISSA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THE PROPERTY HAS BEEN ALTERED IN THE FOLLOWING

MANNER.

1. THE DOCK HAS BEEN REPLACED ON THE EXISTING PILING AND STAIRS ADDED TO THE SOUTH END.

FBC(2014) 105.3.1.4.4

1. WATER LINES INSTALLED ON DOCK.

FBC(2014) 105.3.1.4.5

1. ELECTRICAL SERVICE ADDED TO DOCK.

FBC(2014) 110.6

THE REQUIRED INSPECTIONS FOR THIS WORK WERE NOT

DONE.

.-----

CASE NO: CE15111269
CASE ADDR: 1117 NW 4 AVE
OWNER: MAYNARD, JUNIOR
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

DURING AN ONSITE INSPECTION OF THIS PROPERTY FOR A REQUEST TO VOID A EXPIRED FENCE PERMIT I NOTICED WORK HAD BEEN DONE:

- 1. WINDOW AND DOOR REPLACEMENT.
- 2. KITCHEN AND BATH PLUMBING FIXTURE REPLACEMENT.
- 3. ELECTRICAL SERVICE UPGRADE.
- 4. PLUMBING PIPE TIED INTO CLEAN OUT CAP.
- 5. IT APPEARS THE FLAT ROOF HAS BEEN REROOFED.
- 6. THERE IS A WOOD FENCE THAT WAS NOT PERMITED.

12/23/15 A REVIEW OF THE ORIGINAL PLAN AND THE ATF PLAN SUBMITTED SHOWS:

- 1. THE LAUNDRY WAS A CLOSET AND THE PORCH HAS BEEN CONVERTED TO A BEDROOM.
- 2. THE FRONT ENTRANCE HAS BEEN RELOCATED. THIS CAN BE SEEN IN PHOTOS ON BCPA WEBSITE.
- 3. THE A/C SYSTEM HAS BEEN ALTERED. DUCT WORK HAS BEEN ADDED TO THE BEDROOM ADDITION.
- 4. THE A/C AIR HANDLER AND CONDENSING UNITS REPLACED.

\_\_\_\_\_\_

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT

OWNER: TANGIERS INVESTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE CARPORT HAS BEEN ENCLOSED.
- 2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER.

### FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS, MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS, AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR COMPLIANCE WITH THE TECHNICAL CODES AND OTHER APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION.

-----

CASE NO: CE15082171
CASE ADDR: 2841 SW 9 ST

OWNER: VERNEUS, ALPHONSINE H/E

GASTON, IBRAM

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEN CONVERTED TO AN EFFICIENCY APARTMENT WITH A BATHROOM.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A BATHROOM IN THE DEN WITHOUT ACQUIRING THE REQUIRED PERMITS.

#### FBC (2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED THE ELECTRICAL SYSTEM IN THE COVERTED DEN TO EFFICIENCY WITHOUT A PERMIT.

### FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINNING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A CENTRAL A/C CONDENSOR UNIT WITHOUT THE REQUIRED PERMIT.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. CONVERTED DEN TO AN EFFICIENCY.

### FBC(2014) 116.2.1.2.5

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

FIRE DAMAGE IN THE BUILDING IS A POTENTIAL LIFE AND SAFETY HAZARD SINCE THE BUILDING IS STILL ENERGIZED AND OCCUPIED.

-----

CASE NO: CE16011458

CASE ADDR: 2307 N OCEAN BLVD OWNER: KERR-ROLLE, SWABY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

REMODELING OF STRUCTURE, INTERIOR AND EXTERIOR.

- 1. REMODELING INTERIOR WALL, REMOVING WALL COVERING AND REINSTALLING THROUGHOUT INCLUDING BATHROOMS, KITCHENS AND OTHER LIVING AREAS.
- 2. INSTALLED PERMANENT STRUCTURE ON EXTERIOR WALLS.

# FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF PLUMBING FIXTURES INCLUDING TOILETS, FAUCETS, PLUMBING LINES, VALVES, WASTE LINES. PLUMBING ASSOCIATED WITH BATHROOM AND KITCHEN REMODELING.

# FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION AND REPLACEMENT OF FIXTURES, OUTLETS, SWITCHES, BREAKER PANELS AND DISCONNECTS.

#### FBC(2014) 105.3.1.5

SUBMIT DRAWINGS AND A SCOPE OF WORK COVERING STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

#### FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. ADDING/ALTERING THE COOLING AND HEATING SYSTEM.

## FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

2. ALTERING KITCHEN AND BATHROOM EXHAUST SYSTEM.

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS.

### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

ONSITE INSPECTION WILL BE REQUIRED TO VERIFY PERMIT APPLICATION REQUIREMENTS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF MULTI-FAMILY TO ASSIGNED LIVING FACILITY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT

\_\_\_\_\_\_

CASE NO: CE16070135

CASE ADDR: 4040 GALT OCEAN DR # 1105

OWNER: TALERICO, FRANK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF RESIDENTIAL CONDOMINIUM UNITS TO THAT OF A BUSINESS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

THE CONDOMINIUM UNITS ARE BEING RENTED FOR SOCIAL EVENTS AND GATHERINGS. CHANGE TO BUSINESS USES ALLOWS OCCUPANCY OF UP TO 49 OCCUPANTS AS REGULATED BY THE GUIDELINES OF FLORIDA BUILDING CODE WHICHEVER IS LESS. OCCUPANCY OF 50 OR MORE REQUIRES CHANGE OF USE TO THAT OF ASSEMBLY AS REGULATED BY THE GUIDELINES OF FLORIDA BUILDING CODE WHICHEVER IS LESS.

\_\_\_\_\_\_

CASE NO: CE16020033 CASE ADDR: 315 SE 11 AV

OWNER: ATLANTIC LOFT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. COMMENCED THE ILLEGAL CONSTRUCTION OF AN ATTACHED EXTERIOR LAUNDRY CLOSET ON LEFT ELEVATION OF STRUCTURE.

### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED PLUMBING SUPPLY AND WASTE LINES TO SERVICE ILLEGALLY CONSTRUCTED LAUNDRY CLOSET.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED ELECTRICAL CIRCUITS TO SERVICE ILLEGALLY CONSTRUCTED LAUNDRY CLOSET. INCLUDES 220V CIRCUIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16050712 CASE ADDR: 2308 NW 6 CT

OWNER: SANTORSOLVA, VITO MICHELE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED HURRICANE SHUTTERS ON EXTERIOR WALL OPENINGS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF CHAIN LINK FENCE.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16050853 CASE ADDR: 1301 NW 18 CT

OWNER: 2771 LLC INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THE ROOF ON THIS RESIDENCE WAS REPLACED WITHOUT

PERMIT BETWEEN 2012 AND 2013.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE16061700 CASE ADDR: 1553 NW 15 AVE

OWNER: 2771 LLC INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INSTALLATION OF WALL COVER IN WET SHOWER AREAS.
- 2. KITCHEN REMODEL, PERMIT WAS VOIDED.

# FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF PLUMBING FIXTURES, KITCHENS AND BATHROOMS.
- 2. REPLACED HOT WATER HEATER.
- 3. INSTALLATION OF WATER SUPPLY LINES IN LAUNDRY ROOM.

# FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF BREAKER CIRCUIT PANEL.
- 2. INSTALLATION OF RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6)

GFI REQUIRED AS PER NEC 108.8.

R314.3.1 WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

#### FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. REPLACEMENT OF SPLIT A/C MECHANICAL SYSTEM.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE16070025

CASE ADDR: 401 RIVIERA ISLE 503 OWNER: BROOKS, CHRISTOPHER

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS, DEMOLITION AND REMODELING WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING AN ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY
REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE
REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

# FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

#### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

### FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.